


Solid Edge SEEC – Working Offline

March 2020



Working Offline

- Offline mode can be set on from Solid Edge Cache Assistant
- 2. Select Cache Assistant and if necessary select new Workspace
 - E.g. create different cache Workspaces for different projects
- 3. Download files you want to work with in Offline mode
 - This can be done either by opening the model or assembly to Solid Edge or by selecting Download from Cache Assistant
- 4. Check out the files you want to modify in Offline mode



Update Manage Cache Working Mode Cache Status	pdate Synchronize Check Check In New	Download	Me AII Cc
	m Revision Display Name Item Ty	p	

Item Revision Display Name		Item Type		ltem II	0	Revision	
All values		All Values		All Val	ues	All Values	
🗐 001561/C;1-r y		Tosti Itom		00156		С	
001300/A;1		ору			5	А	
🕒 001567/A;1		Columns 7 Font 8 Find 4 Freeze Columns 5				А	
🕒 001568/A;1						А	
🕒 002204/A;1						А	
🔄 002205/A;1						А	
🔄 002206/A;1						А	
	Co	Column Width 🔹					
	Hi	Hide Preview					
	Pr						
	Up	odate S			-		
	Sy	nchron					
	Cł	neck Out					
	Cancel Che						
	Cł	neck In	Cache Assistant				
documents selected	De	elete from	Cha	ck Out			
aocuments selected	O	pen					
	Sh	iow Revis	Pres).			





Working Offline

- 1. Select Synchronize from Cache Assistant and then Offline Mode
- 2. Cache Assistant can be then closed, Solid Edge Data is now ready to be used in Offline mode
- 3. Now Solid Edge can be connected to TC Database again, by selecting Working Online and Check In documents. If new items are added to assemblies while working offline, select Check in new and give mandatory Item information.

